






CP1602DK



CP1602DK



A x36
Spec: $\phi 8 \times L30$



B x24
Spec: $\phi 7 \times L30$



C x24
Spec: $\phi 15 \times H12$



D x2
Spec: $\phi 6 \times L28$




E x2
Spec: $\phi 12 \times H9$



F x2
Spec: $\phi 6 \times L30$



G x2
Spec: 10g




H x1
Spec: L400



I x6
Spec: $\phi 6 \times L8$



J x16
Spec: $\phi 3.8 \times L25$



K x4
Spec: $\phi 3.5 \times L35$



L x6
Spec: $\phi 3.5 \times L16$



M x6
Spec: H13



O x2
Spec: M4 $\times$ L25




P x28
Spec:



Q x1
Spec:





AAA x4
Spec: $\phi 3.8 \times L12$



1


2






3


4






5


6






7


8






9

10





11

12

