





CP1704DK



CP1704DK



A x50
Spec: $\varnothing 8 \times 30$



B x42
Spec: $\varnothing 7 \times L30$



C x42
Spec: $\varnothing 15 \times H12$



D x10
Spec: $\varnothing 6 \times L28$




E x10
Spec: $\varnothing 12 \times H9$




F x2
Spec: $\varnothing 6 \times 30$




G x2
Spec: 10g




H x12
Spec: $\varnothing 3.5 \times L35$



I x3
Spec: L400



J x12
Spec: $\varnothing 6 \times L9$



K x10
Spec: $5/16 \times L35$



L x10
Spec: $M14 \times 8.2 \times 1$




M x52
Spec:



N x1
Spec: 5#





AAA x12
Spec: $\varnothing 3.8 \times L12$



1


2






3


4






5


6






7


8






9

10





11

12

