






CP1708I



CP1708I




A x8
Spec: $\varnothing 8 \times 30$



B x12
Spec: $\varnothing 7 \times L30$




C x12
Spec: $\varnothing 15 \times H12$



D x4
Spec: $\varnothing 6 \times L28$



E x4
Spec: $\varnothing 12 \times H9$




F x4
Spec: $\varnothing 3.5 \times L35$



G x1
Spec: 10g



H x6
Spec: $\varnothing 6 \times L8$



I x1
Spec: L400



J x4
Spec: $\varnothing 3.5 \times L16$



K x4
Spec: H13



L x12
Spec: M6 $\times 15$



M x12
Spec: $\varnothing 8 \times \varnothing 14$




N x16
Spec:



O x8
Spec: $\varnothing 15$





AAA x4
Spec: $\varnothing 3.8 \times L12$




1


2






4






5


6






7

8





9

10

