






CP1501TV3



CP1501TV3




A x16
Spec: $\varnothing 8 \times 30$




B x16
Spec: $\varnothing 7 \times L30$



C x16
Spec: $\varnothing 15 \times H12$




D x1
Spec: 10#




E x2
Spec: 048#



F x4
Spec: $\varnothing 4 \times 6.5$



G x18
Spec: $\varnothing 3.5 \times L16$



H x18
Spec: H13



I x10
Spec: $\varnothing 8 \times \varnothing 18$




J x8
Spec: $\varnothing 20 \times H12$



K x8
Spec: $\varnothing 5 \times L19$



L x4
Spec: $\varnothing 60 \times 25$



M x3
Spec: L188*30




N x4
Spec: M4*L25



N1 x2
Spec: M4*L28



O x1
Spec: 10g



P x4
Spec: 068#



Q x8
Spec: 3.8*L16



R x6
Spec: M6*15



S x4
Spec: M6*32



T x16
Spec: $\varnothing 17$




U x4
Spec: 15*15



V x4
Spec: $\varnothing 10 \times H1$





W x2
Spec: $\varnothing 4 \times 8$



1


2







3

4






5





6



7

8





10

